137 Harley Street, London W1G 6BG Tel: +44 20 7034 3070 Fax: +44 20 7034 3071 Email: certification@fetalmedicine.org

Wojciech Kocon Kleczewska 41 Warszawa 01-826 Poland

Jul 05, 2018 FMF ID: 74510

Preeclampsia screening - Measurement of uterine artery PI

Dear Wojciech Kocon,

Thank you for submitting your logbook of 3 images. I examined each image for the following criteria: sagittal section, angle of insonation angle less than 30 degrees, velocity more than 60 cm/s, and sample volume 2.0 mm (see table below).

	Image number		
Criteria	1	2	3
Sagittal section	4	1	✓
Insonation angle < 30°	✓	✓	✓
Velocity > 60 cm/s	✓	√	✓
Sample Volume 2.0 mm	1	√	1

Legend: ✓ = pass X = fail -- = not possible to assess

Your images are satisfactory. Your software license will include the assessment of **uterine artery flow** in the risk calculation for preeclampsia and your name will appear on the list of sonographers certified for assessment of uterine artery flow.

Best wishes,

Olga Khoury Carter